








2332 Cathy Lane
 Jasper, Indiana
 47546
 800.876.2120
 812.482.9318 Fax
 www.versteel.com

Thank you for your purchase. Versteel hopes that you have many great years of use from this table and from all our products. If you have questions that these instructions do not answer, please call customer service at 800.876.2120



 DOCUMENT CONTAINS 2 PAGES	ASSEMBLY INSTRUCTIONS: PACES APEX TABLE																			
<p>COMPONENTS:</p> <table border="0"> <thead> <tr> <th></th> <th>COMPONENTS:</th> <th>QUANTITY:</th> </tr> </thead> <tbody> <tr> <td>①</td> <td>LEG ASSEMBLY</td> <td>4</td> </tr> <tr> <td>②</td> <td>TOP PLATE</td> <td>1</td> </tr> <tr> <td>③</td> <td>5/16-18 X 1 FLAT HEAD CAP SCREW</td> <td>8</td> </tr> <tr> <td>④</td> <td>#10 X 5/8 WOOD SCREW</td> <td>12</td> </tr> <tr> <td>⑤</td> <td>TABLE TOP</td> <td>1</td> </tr> </tbody> </table>		COMPONENTS:	QUANTITY:	①	LEG ASSEMBLY	4	②	TOP PLATE	1	③	5/16-18 X 1 FLAT HEAD CAP SCREW	8	④	#10 X 5/8 WOOD SCREW	12	⑤	TABLE TOP	1		
	COMPONENTS:	QUANTITY:																		
①	LEG ASSEMBLY	4																		
②	TOP PLATE	1																		
③	5/16-18 X 1 FLAT HEAD CAP SCREW	8																		
④	#10 X 5/8 WOOD SCREW	12																		
⑤	TABLE TOP	1																		
<p>TOOLS REQUIRED:</p> <table border="0"> <tbody> <tr> <td>①</td> <td>1/4" HEX WRENCH OR DRIVER</td> </tr> <tr> <td>②</td> <td>CORDLESS SCREWDRIVER AND PH2 BIT</td> </tr> </tbody> </table>	①	1/4" HEX WRENCH OR DRIVER	②	CORDLESS SCREWDRIVER AND PH2 BIT																
①	1/4" HEX WRENCH OR DRIVER																			
②	CORDLESS SCREWDRIVER AND PH2 BIT																			
<p>ASSEMBLY: STEP ONE</p> <p>MOUNT LEGS TO TOP PLATE USING (8) 5/16-18 X 1 FHCS AND HEX WRENCH.</p>	 <p style="text-align: center;">DETAIL A</p>																			



ASSEMBLY: STEP TWO

PLACE TOP UPSIDE DOWN ON SMOOTH SURFACE. ATTACH TOP PLATE/LEG ASSEMBLY USING (12) WOOD SCREWS AND CORDLESS SCREWDRIVER.

